Height-Adjusting Elements • orienting 25120.0232




Product Description

For levelling of machines and installations when bearing surfaces are not parallel. For vertical adjustment, the self-locking height-adjusting elements are fitted with a fine-pitch thread. All elements have a throughgoing bore for fastening purposes. A turn-out lock serves as height limit for the maximum adjustment height.

Material

· Heat-treated steel, zinc-plated by galvanization, chromalized

Drawing



Erwin Halder KG

Order information

| Dimensions | | | | | Stroke | For screw | Load capacity | Load capacity | I | Art. No. |
|------------|----------------|-----------|----------------|----------------|----------------|-----------|-----------------|---------------|-----|------------|
| d₁ | d ₂ | d_3 | I ₁ | l ₂ | l ₃ | | for static load | max. | _ | |
| | _ | - | ~ | ~ | ~ | | max. | | | |
| [mm] | | | | | [mm] | [mm] | [kN] | [kN] | [g] | |
| 17.5 | 58 | M40 x 1,5 | 44 | 53 | 9 | M16 | 210 | 136 | 775 | 25120.0232 |

Accessories


| | For height adjusting element size d_2 | Dimensions of sickle spanner DIN 1810, form A | i | Art. No. | | | | | | | |
|--|---|---|-----|------------|--|--|--|--|--|--|--|
| | [mm] | [mm] | [9] | | | | | | | | |
| sickle spanner for vertical adjustment | | | | | | | | | | | |
| | 58 | 58 – 62 | 250 | 25120.0984 | | | | | | | |



www.halder.com Page 1 of 3

Published on: 3.2.2024

Application example





Compliance

RoHS compliant

Compliant according to Directive 2011/65/EU and Directive 2015/863.

Does not contain SVHC substances

No SVHC substances with more than 0.1% w/w contained - SVHC list [REACH] as of 23.01.2024.

Does not contain Proposition 65 substances

No Proposition 65 substances included. https://www.P65Warnings.ca.gov/

Free from Conflict Minerals

This product does not contain any substances designated as "conflict minerals" such as tantalum, tin, gold or tungsten from the Democratic Republic of Congo or adjacent countries.



www.halder.com Page 3 of 3
Published on: 3.2.2024

Erwin Halder KG